



JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

April 18, 2007

Supervisor AOB

Mine Name: UTU-79911-KSC 1&2

Operator Name: KSC Rocks

Permit number: M0410035

Inspection Date: April 5, 2007

Time: 9:00 am

Inspector(s): Lynn Kunzler, DOGM

Other Participants: Michael Jackson, BLM, Steve Sorenson, Operator

Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection while in the area.

Inspection Summary:

The BLM has determined that the material Mr. Sorenson is mining is 'common variety' and is being held as a sale by the BLM. Currently about 1/4 acre has been disturbed by excavating material from past sales. The BLM would like Mr. Sorenson to drill a series of core holes (exploration work) to determine that marketable material is in fact still available on site, before the operator does significant disturbance. These holes would only be 15-20 feet deep. Mr. Sorenson is willing to do this but is having trouble finding a drill. He will coordinate this activity with the BLM.

Topsoil has been salvaged and is stockpiled adjacent to the current pit. A small waste pile is also located on the north end of the pit

Photos were taken to document site conditions.

Conclusions and Recommendations:

Continue to monitor this site when in the area.

Inspector's Signature

LK:pb

O:\M041-Sevier\S0410035-UTU-79911\inspections\Insp-04052007.doc